DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-003607 Address: 333 Burma Road **Date Inspected:** 29-Jul-2008

City: Oakland, CA 94607

Project Name: SAS Superstructure OSM Arrival Time: 1420 **OSM Departure Time:** 2230 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Zhu Zhong Hai No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No

Yes No N/A **Delayed / Cancelled: Bridge No:** 34-0006 **Component:** deck panels / skin plates and stiffeners/side pl

Summary of Items Observed:

Heavy Duty Machine Shop – Bay 3:

Caltrans Quality Assurance Inspector George Goulet (QA Inspector) observed ZPMC workers grinding on the following deck panels: DP378-001, DP459-001, DP135-001, and DP351-001. No welding was observed being performed. Present in this bay were ABF QC Kevin Ding, approximately 19 workers, and 28 panels.

Tower Shop – Bay 1

QA Inspector observed ZPMC personnel performing fit-up of stiffeners to SSD1-SA173/SA16 skin plate assembly and 200mm stitch weld in 500mm using SMAW with 7018 rod. Present in this bay were ABF QC's You Yuan Mao, Zhang Jiadi, ZPMC CWI Zhu Zhong Hai, and approximately 60 workers.

Sub Assenbly – Bay 4

QA Inspector performed 10% verification final MT on the following rib to side plate welds SP195-001 - welds 002 to 013, SP650-001 - welds 022 to 031, SP646-001 - welds 022 to 031, SP308-001 welds 013 to 024, and SP302-001 - welds 002 to 013. No apparent indications were observed. Approximately 40 workers were present in this bay.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)





Summary of Conversations:

No significant conversations on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco, 138-1694-2685, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer